


Schedule of Accreditation

issued by

United Kingdom Accreditation Service

2 Pine Trees, Chertsey Lane, Staines-upon-Thames, TW18 3HR, UK

 <p>0197 Type C Inspection Body</p> <p>Accredited to ISO/IEC 17020:2012</p>	Environtec Ltd Issue No: 026 Issue date: 20 April 2017	
	Environtec House The Street Hatfield Peverel Chelmsford Essex CM3 2EJ	Contact: Mr J J Meates Tel: +44 (0)1245 381900 Fax: +44 (0)1245 381666 E-Mail: enquiries@environtec.com Website: www.environtec.com
Inspection performed at/from the locations specified below		

Locations covered by the organisation and their relevant activities

Location details		Activity	Location code
Address Environtec House The Street Hatfield Peverel Chelmsford Essex CM3 2EJ	Local contact Mr J J Meates Tel: +44 (0)1245 381900	Asbestos: Surveying	A
Address Construction House Hermitage Way Mansfield Nottingham NG18 5ES	Local contact Mr Adam Lomas Tel: +44 (0)1623 757189	Asbestos: Surveying	B
Address 11 Owler Ings Road Brighouse West Yorkshire HD6 1EJ	Local contact Mr I Ashby Tel: +44 (0)1484 711133	Asbestos: Surveying	C
Address Second Floor Unit 3 Cadzow Park 82 Muir Street Hamilton ML3 6BJ	Local contact Mr John Malone Tel: +44 (0)1698 421898	Asbestos: Surveying	D
Address Unit H27 The Avenues Eleventh Avenue North Team Valley Trading Estate Gateshead Tyne and Wear NE11 0NJ	Local contact Mr David Carnaffin Tel: +44(0)191 487 3236	Asbestos: Surveying	E



0197

Type C
Inspection Body

Accredited to
ISO/IEC 17020:2012

Schedule of Accreditation
issued by
United Kingdom Accreditation Service
2 Pine Trees, Chertsey Lane, Staines-upon-Thames, TW18 3HR, UK

Environtec Ltd

Issue No: 026 Issue date: 20 April 2017

Inspection performed by the Organisation at/from the locations specified

Location details	Activity	Location code
<p>Address 5a Turner Street Newport South Wales NP19 7BA</p> <p>Local contact Ian Faul +44(0)163 326 2922</p>	<p>Asbestos: Surveying</p>	<p>F</p>



0197
Type C
Inspection Body
 Accredited to
 ISO/IEC 17020:2012

Schedule of Accreditation
 issued by
United Kingdom Accreditation Service
 2 Pine Trees, Chertsey Lane, Staines-upon-Thames, TW18 3HR, UK

Environtec Ltd
Issue No: 026 Issue date: 20 April 2017

Inspection performed by the Organisation at/from the locations specified

DETAIL OF ACCREDITATION

Field of Inspection	Type and Range of Inspection	Methods and Procedures	Location Code
Surveying for asbestos in premises	Management survey: (domestic, commercial and industrial premises)	Health and Safety Executive Asbestos: The survey guide (HSG 264, 2012) Documented In-House Inspection Method in Procedures Manual ETP 002	A, B, C, D, E, F
	Refurbishment and demolition survey: (domestic, commercial and industrial premises)	Documented In-House Inspection Method in Procedures Manual ETP 002	A, B, C, D, E, F
	Reinspection of identified or suspected asbestos containing material in surveyed premises	Documented In-House Method in Procedures Manual ETP 002 (based on guidance documented in Appendix 5 of HSG 227 (2004)	A, B, C, D, E, F
END			